


# Gantry/Camera Replacements



- Replacing 17 gantries on Westbound Bridge (BB-2819)
  - Condition inspection findings showed defects in the structures and the LED signals were at the end of their expected life cycle
  - Circular monotube gantry design is replacing square truss gantry
  - Replacing attachments – Lane Use Control Signals, Signs, and CCTV Cameras

